
Treo 600 - Removing Buzzing

English Version

Author: XiaoBin (shoppingxiao)

1. Prepare the project

- a. Install the 3.05 firmware. It can improve the buzzing but not much.
- b. Backup your TREO 600
- c. Remove the SIM and SD
- d. Remove the stylus
- e. Prepare a clean space for your work
- f. Shut down your TREO 600
- g. Prepare the tools (Figure 1), screwdriver (This costs 3.49, too expensive in UK), toothpick (for rubber caps), scissors (use for cutting foil paper).




Figure 1

2. NOW, we start.

a. use the toothpick to remove the rubber cap. Toothpick is not metal to avoid breaking the caps. Figure 2 shows the positions of caps (screws)



Figure 2

b. remove outside plastic antenna before you open TREO (Figure 3)



Figure 3

c. Open the TREO Figure 4



Figure 4

d. As the Figure 5 size to cut a piece of the foil paper. 15mm is width, length can be doubled, but I use more. Do not cut paper too long. You can't install the folded wire back, if too thick.




Figure 5

e. Fold up the foil paper. (Figure 6) Install it back to the original position.



Figure 6

h. We finished. Install the screws and other things like original. Easy? I feel that after my installation

3. Test

- a. Restore your data
- b. Open TREO 600 my signal is good. I called my classmates, even calling to China. Test takes me entire afternoon. All they said that everything is OK.

This document was created with Win2PDF available at <http://www.daneprairie.com>.
The unregistered version of Win2PDF is for evaluation or non-commercial use only.